

Installation and Service Instructions for 56/143-5TC Double C-Face Coupler (Rev C)

For replacement parts refer to sheet part number 8-078-906-07. Instructions and parts list also available at www.rexnord.com/stearns.




Figure 1 Position hub to Y as shown: Y=.32" (8.1mm) for 1 & 2 disc (1.5 - 15 lb-ft) Y=.19" (4.8mm) for 3 disc (20 & 25 lb-ft)

Important

Please read these instructions carefully before installing, operating, or servicing your brake. Failure to comply with these instructions could cause injury to personnel and/or damage to property if the brake is installed or operated incorrectly. For definition of limited warranty/ liability, contact Leeson Electric Corporation, P.O. Box 241, 2100 Washington Street, Grafton, WI 53024-0241, (262) 377-8810.

Caution

- Installation and servicing must be made in compliance with all local safety codes including Occupational Safety and Health Act (OSHA). All wiring and electrical connections must comply with the National Electric Code (NEC) and local electric codes in effect.
- Do not operate the brake in atmospheres containing explosive gases or dusts.
- 3. To prevent an electrical hazard, disconnect power source before working on the brake. If power disconnect point is out of sight, lock disconnect in the *off* position and tag to prevent accidental application of power.

 Make certain power source conforms to the requirements specified on the brake nameplate.

5/16" nut driver

3/16" hex wrench

3/8" hex wrench

1/4" screwdriver

- Be careful when touching the exterior of an operating brake. Allow sufficient time for brake to cool before disassembly. Surfaces may be hot enough to be painful or cause injury.
- Do not operate brake with housing removed. All moving parts should be guarded.
- Installation and servicing should be performed only by qualified personnel familiar with the construction and operation of the brake.
- 8. For proper performance and operation, only genuine Stearns parts should be used for repairs and replacements.
- After usage, the brake interior will contain burnt and degraded friction material dust. This dust must be removed before servicing or adjusting the brake.

DO NOT BLOW OFF DUST using an air hose. It is important to avoid dispersing dust into the air or inhaling it, as this may be dangerous to your health. a) Wear a filtered mask or a respirator while removing dust from the inside of a brake.

Torque wrench

b) Use a vacuum cleaner or a soft brush to remove dust from the brake. When brushing, avoid causing the dust to become airborne. Collect the dust in a container, such as a bag, which can be sealed off.

10. Caution! While the brake is equipped with a manual release to allow manual shaft rotation, the motor should not be run with the manual release engaged, to avoid overheating the friction disc(s).


Warning! Do not apply overhung or side load to brake output shaft


General Description

5/16" hex wrench

8" adjustable wrench

The 56,700 Series coupler is a spring-set, electrically released brake, containing either one or more rotating friction discs (4) driven by a hub (16) mounted on the motor shaft. The double C-face allows the brake to directly couple a C-face motor to a C-face gear reducer.





TROUBLESHOOTING

COIL FAILURE							
SUPPLY VOLTAGE CAUSE	SUPPLY VOLTAGE CORRECTION						
Line voltage >110% of coil rating	Reduce voltage or replace with proper rated coil						
Excessive voltage drop during inrush time	Increase current rating of power supply.						
WIRING CAUSE	WIRING CORRECTION						
Leadwires interfering with plunger pull-in	Reroute wiring away from plunger and other moving components.						
Excessive voltage drop during inrush time	Increase leadwires size from power supply						
Coil leadwire shorted to ground	Replace coil or leadwire and protect with wire sleeving						
SOLENOID ASSEMBLY CAUSE	SOLENOID ASSEMBLY CORRECTION						
Plunger not seating flush against solenoid frame	Loosen solenoid mounting screws and reposition frame to allow full face contact						
Plunger cocked in coil preventing pull-in	Realign solenoid frame						
Excessive solenoid/plunger wear at mating surface	Replace solenoid assembly						
Broken shading coils	Replace solenoid assembly						
WORN PARTS CAUSE	WORN PARTS CORRECTION						
Excessive wear of solenoid link arm and/ or shoulder bolt	Replace link arm and link bolt; also inspect plunger thru-hole for elongation						
Plunger guides worn down and interfering with plunger movement	Replace guides						
APPLICATION CAUSE	APPLICATION CORRECTION						
Machinery cycle rate is exceeding brake rating	Reduce brake cycle rate or use alternate control method						
High ambient temperature (>110%) and thermal load exceeding coil insulation rating	Use Class H rated coil and /or find alternate method of cooling brake						
Brake coil wired with windings of an Inverter motor or other voltage/current limiting device	Wire coil to dedicated power source with instantaneous coil rated voltage						
MISCELLANEOUS CAUSE	MISCELLANEOUS CORRECTION						
Wrong or over tightened torque	Replace with proper spring or refer to Installation section for proper spring height						
Excessive air gap	Reset, refer to Installation Section 4						

EXCESSIVE WEAR / OVERHEATING						
AIR GAP CAUSE	AIR GAP CORRECTION					
Low solenoid air gap	Reset air gap (refer to Air Gap Adjustment)					
Disc pack dragging	Inspect endplate, hub and discs for dirt, burrs, wiring and other sources of interfer- ence preventing disc "float"					
CYCLE RATE CAUSE	CYCLE RATE CORRECTION					
Brake "jogging" exceeding coil cycle rate	Reduce cycle rate or consider alternate control method					
Thermal capacity is being exceeded	Reduce cycle rate, use alternate control method or increase brake size					
ALIGNMENT CAUSE	ALIGNMENT CORRECTION					
Broke endplate not concentric to motor C-Face	Motor register must be within .004" on concentricity;					
Motor shaft runout is excessive	Must be within .002"; runout; consult motor manufacturer					
Brake is being operated on a incline greater than 15° above or below horizontal	Vertical separator springs must be used to prevent discs from becoming cocked					
WORN PARTS CAUSE	WORN PARTS CORRECTION					
Friction disc excessively worn (disc can wear to 1/2 original thickness or .093")	Replace friction discs.					
Endplate, stationary disc or pressure plate warped	Replace warped or worn component					
Linkages and/or pivot pins worn	Replace all worn components					
Motor shaft endfloat excessive	Endfloat must not exceed .020"; consult motor manufacturer					
HUB CAUSE	HUB CORRECTION					
Burr on hub interfering with disc "float"	File off burr					
Set screw backed out and interfering with disc	Retighten set screw; use Loctite® 242 to help secure					
MISCELLANEOUS	MISCELLANEOUS					
Solenoid plunger not pulling completely	Check line voltage (±10% of nameplate rating) or replace worn solenoid assembly					
Wiring is restricting disc pack movement	Reroute wiring					
Excessive stop time (2 seconds or greater)	Increase brake size/torque or use alter- nate control method					
High Ambient temperature (in excess of 110°F)	Reduce cycle rate or use alternate method of cooling					
Moisture in brake	Remove drain plug (WASHGUARD brakes only). After fluid has drained replace plug					

	Torque Ib. ft.	Leeson Part Number	Stearns Part Number	Brake Coil Rating (VAC)	NEMA Enclosure	Brake Bore/ Shaft Diameter (X/U)	NEMA Frame Size	Dimension A
	3	175563.00	1056711051PF	115/208-230	2	5/8" / 5/8"	56C	4.91"
		175564.00	1056711051QF	208-230/460	2	5/8" / 5/8"	56C	4.91"
		175565.00	1056711051NF	575	2	5/8" / 5/8"	56C	4.91"
		175566.00	1056714051PF	115/208-230	4X	5/8" / 5/8"	56C	4.94"
		175567.00	1056714051QF	208-230/460	4X	5/8" / 5/8"	56C	4.94"
ERS		175568.00	1056714051NF	575	4X	5/8" / 5/8"	56C	4.94"
	6	175569.00	1056721081PF	115/208-230	2	7/8" / 5/8"	56C/143-5TC	4.91"
H		175570.00	1056721081QF	208-230/460	2	7/8" / 5/8"	56C/143-5TC	4.91"
NUMBE		175571.00	1056721081NF	575	2	7/8" / 5/8"	56C/143-5TC	4.91"
Ě		175572.00	1056724081PF	115/208-230	4X	7/8" / 5/8"	56C/143-5TC	4.94"
PART		175573.00	1056724081QF	208-230/460	4X	7/8" / 5/8"	56C/143-5TC	4.94"
ΡA		175574.00	1056724081NF	575	4X	7/8" / 5/8"	56C/143-5TC	4.94"
	10	175575.00	1056731081PF	115/208-230	2	7/8" / 5/8"	56C/143-5TC	4.91"
		175576.00	1056731081QF	208-230/460	2	7/8" / 5/8"	56C/143-5TC	4.91"
		175577.00	1056731081NF	575	2	7/8" / 5/8"	56C/143-5TC	4.91"
		175578.00	1056734081PF	115/208-230	4X	7/8" / 5/8"	56C/143-5TC	4.94"
		175579.00	1056734081QF	208-230/460	4X	7/8" / 5/8"	56C/143-5TC	4.94"
		175580.00	1056734081NF	575	4X	7/8" / 5/8"	56C/143-5TC	4.94"
	15	175581.00	1056741071QF	208-230/460	2	7/8" / 7/8"	143-5TC	4.91"
	15	175582.00	1056744071QF	208-230/460	4X	7/8" / 7/8"	143-5TC	4.94"